

# FLEXKIT® SR

## Accessories for FLEXTRACE® SR long line heating cables

### Description

- OMERIN provides a complete range of 3 FLEXKIT® SR connection kits:
  - > the FLEXKIT® SR POWER power supply kit
  - > the FLEXKIT® SR JUNCTION junction kit
  - > the FLEXKIT® SR END termination kit

These kits are designed for use with FLEXTRACE® SR long line heating cables.

• FLEXKIT® SR kits are available in MEDIUM and LARGE size, perfect for the different AWG ratings of FLEXTRACE® SR long line heating cables. Please consult our FLEXKIT® SR data sheet for more information about the range.

• FLEXKIT® SR kits can be installed at temperatures down to -30°C. We recommend that you store the products in a dry location away from frost and humidity.

### Accessories for FLEXKIT® SR connection kits

#### Warning labels

##### ELECTRICAL HEAT TRACING

P/N: 3E060010




• The self-adhesive warning label indicates the presence of an electrical heat tracing system along the length of the pipeline. The labels are mandatory to ensure that technicians take all necessary safety precautions before working on the installation. They should be applied at the regular distances indicated in the FLEXTRACE® SR system installation manual.

One warning label is supplied in each FLEXKIT® SR kit. Additional labels are sold separately. Ensure that you have a sufficient quantity of labels before installing the FLEXTRACE® SR system.

#### Fiberglass tape

##### ROLL

P/N: 3E070110




• **Dimensions: width 1/2" x 100'**

Fiberglass tape is used to hold the FLEXTRACE® SR long line heating cables in a stable, fixed position along the pipeline.

#### Fiberglass tape

##### ROLL

P/N: 3E070120




• **Dimensions: width 1" x 100'**

Fiberglass tape is used to hold the FLEXTRACE® SR long line heating cables in a stable, fixed position along the pipeline.

#### Aluminum tape

##### ROLL

P/N: 3E070210




• **Dimensions: width 2" x 164'**

Aluminum tape is used to hold the FLEXTRACE® SR long line heating cables in place while ensuring homogeneous diffusion of heat over the whole contact surface between the tape and the pipe surface.

#### Serrated clamp collar

##### META

P/N: 3E070010



• **Dimensions: diameters from 2" up to 14.6"**

Serrated clamp collars are used to secure the FLEXTRACE® SR long line heating cables to the pipeline near the valve and bend coupling flanges. Their high mechanical strength ensures the heating cable remains in position despite the small bend radius of the cable.

**For further information, please do not hesitate to contact us**

OMERIN USA, Inc. QS Technologies division  
95 Research Parkway - Meriden, Connecticut 06450  
Phone: +1 203-237-2297  
qstech@omerin.com



[www.omerin-usa.com](http://www.omerin-usa.com)